	Type	L #	Hits	Search Text
1	BRS	L1	3808	(((light adj (source tube)) lamp) near5 (mount$3 install$5 replac$5)) and (scanner reader)
2	BRS	L2	1118	1 and ((light adj (source tube)) lamp).ab.
3	BRS	L3	843	(((light adj (source tube)) lamp) near5 (mount$3 install$5 replac$5)) same (scanner reader)
4	BRS	L4	239	3 and "358"/$.ccls.
5	BRS	L5	0	4 and 358/475.ccls
6	BRS	L6	34	4 and 358/475.ccls.
7	BRS	L7	205	4 not 6
8	BRS	L8	604	3 not 4
9	BRS	L9	18	8 and bracket and socket
10	BRS	L10	827	2 not 3
11	BRS	L11	115	10 and "358"/$.ccls.
12	BRS	L12	10	10 and (bracket same socket)
13	BRS	L13	115	11 not 12
14	BRS	L14	37	10 and bracket and socket
15	BRS	L15	3	(((light adj (source tube bulb)) lamp) near8 (mounting installat$3 replacing replacement)) and (full adj rate) and (half adj rate)
16	BRS	L17	0	16 and (((light adj (source tube bulb)) lamp) same socket same bracket)
17	BRS	L18	1	16 and (((light adj (source tube bulb)) lamp)) and (socket same bracket)
18	BRS	L19	2	16 and bracket and socket

19	BRS	L16	25	(((light adj (source tube bulb)) lamp) near8 (mounting installat$3 replacing replacement)) and (first adj carriage) and (second adj carriage) and (removabl$2 removing replacing replacabl$2 attach$5 detach$5)

	Type	L #	Hits	Search Text
20	BRS	L20	76	(((((light adj source) tube bulb) lamp) near8 (mounting installat$3 replacing replacement)) and (first adj carriage) and (second adj carriage) and (removabl$2 removing replacing replacabl$2 attach$5 detach$5)
21	BRS	L21	13421	"76" and bracket and socket
22	BRS	L22	6	20 and bracket and socket
23	BRS	L23	43	20 and bracket
24	BRS	L24	3	(((((light adj source) tube bulb) lamp) near8 (mounting installat$3 replacing replacement)) and (full adj rate) and (half adj rate) and (removabl$2 removing replacing replacabl$2 attach$5 detach$5)
25	BRS	L25	195	((light adj source) tube bulb lamp) with bracket with detachab$2
26	BRS	L26	103300	"26" and socket
27	BRS	L27	57	25 and socket
28	BRS	L28	0	27 and (first adj carriage) and (second adj carriage)
29	BRS	L29	0	27 and (full adj (speed rate)) and (half adj (speed rate))
30	BRS	L30	3	27 and carriage
31	BRS	L31	54	27 not 30
32	BRS	L32	1	"3555268".pn.
33	BRS	L33	591	((light adj source) tube bulb lamp) same bracket same detachab$2
34	BRS	L35	1	34 and scanner
35	BRS	L34	44	((light adj source) tube bulb lamp) same bracket same detachab$2 same socket
36	BRS	L36	412	358/475.ccls.
37	BRS	L37	162	((light adj source) tube bulb lamp) same bracket same removab$3 same socket
38	BRS	L38	2040	((light adj source) tube bulb lamp) same bracket same socket

	DBs	Time Stamp	Comments	Error Definition	Errors
39	USPAT	2004/12/06 16:09			
40	USPAT	2004/12/06 16:11			
41	USPAT	2004/12/06 16:13			
42	USPAT	2004/12/06 16:15			
43	USPAT	2004/12/06 16:15			
44	USPAT	2004/12/06 16:15			
45	USPAT	2004/12/06 16:15			
46	USPAT	2004/12/06 16:16			
47	USPAT	2004/12/06 16:17			
48	USPAT	2004/12/06 16:17			
49	USPAT	2004/12/06 16:19			
50	USPAT	2004/12/06 18:13			
51	USPAT	2004/12/06 16:34			
52	USPAT	2004/12/06 16:40			
53	USPAT	2004/12/06 16:42			
54	USPAT	2004/12/06 16:42			
55	USPAT	2004/12/06 16:42			
56	USPAT	2004/12/06 16:42			
57	USPAT	2004/12/06 16:42			
58	USPAT	2004/12/06 16:44			
59	USPAT	2004/12/06 16:45			

	Type	L #	Hits	Search Text
61	BRS	L61	1	55 and "382"/$.ccls.
62	BRS	L62	15	55 and (flatbed (flat adj bed))
63	BRS	L63	2059	55 not 62
64	BRS	L64	0	63 and "358"/$.ccls.
65	BRS	L65	191	63 and mirror
66	BRS	L66	1868	63 not 65
67	BRS	L67	28	66 and scanning
68	BRS	L68	1840	66 not 67
69	BRS	L69	703	68 and ((light adj source) tube lamp).ab.
70	BRS	L70	45774	(((light adj source) tube lamp) and (attach$5 detach$5 remov$6 mount$3)).ab.
71	BRS	L71	6	70 and (full adj rate) and (half adj rate)
72	BRS	L72	15157	(((light adj source) tube lamp) and (attach$5 detach$5)).ab.
73	BRS	L73	2182	72 and (reading reader scanner scanning)
74	BRS	L74	1708	73 and (frame chassis casing case housing)
75	BRS	L75	359	74 and bracket
76	BRS	L76	77	75 and socket
77	BRS	L77	30	"5038028".uref.
78	BRS	L78	40	50 and (((light adj source) tube bulb lamp) with ((easy easily) near2 (replaced replacement)))
79	BRS	L79	1480	(((light adj source) tube bulb lamp) with ((easy easily) near2 (replaced replacement)))
80	BRS	L81	66	79 and (bracket same socket)
81	BRS	L82	44	79 and scanner

	DBs	Time Stamp	Comments	Error Definition	Errors
61	USPAT	2004/12/06 16:46			
62	USPAT	2004/12/06 16:55			
63	USPAT	2004/12/06 16:55			
64	USPAT	2004/12/06 16:55			
65	USPAT	2004/12/06 16:57			
66	USPAT	2004/12/06 16:57			
67	USPAT	2004/12/06 16:58			
68	USPAT	2004/12/06 16:58			
69	USPAT	2004/12/06 17:02			
70	USPAT	2004/12/06 17:06			
71	USPAT	2004/12/06 17:05			
72	USPAT	2004/12/06 17:07			
73	USPAT	2004/12/06 17:07			
74	USPAT	2004/12/06 17:09			
75	USPAT	2004/12/06 17:09			
76	USPAT	2004/12/06 17:53			
77	USPAT	2004/12/06 18:05			
78	USPAT	2004/12/06 18:16			
79	USPAT	2004/12/06 19:18			
80	USPAT	2004/12/06 18:33			
81	USPAT	2004/12/06 18:44			

	Type	L #	Hits	Search Text
83	BRS	L84	1352	83 not 81
84	BRS	L85	1310	84 not 82
85	BRS	L86	183	85 and bracket
86	BRS	L87	77	86 and (((light adj source) tube bulb lamp) with bracket)
87	BRS	L88	9	79 and "358"/$.ccls.
88	BRS	L80	128	79 and bracket and socket
89	BRS	L89	5	79 and (lamp adj bracket)
90	BRS	L90	1	79 and ((light adj source) adj bracket)
91	BRS	L91	4	79 and "399"/$.ccls.
92	BRS	L92	33	79 and "359"/$.ccls.
93	BRS	L93	90	79 and "250"/$.ccls.
94	BRS	L94	1708	(((light adj source) tube bulb lamp) with ((easy easily) near2 (replaced replacement exchang$3)))
95	BRS	L95	228	94 not 79
96	BRS	L96	2392	(((light adj source) tube bulb lamp) with ((easy easily) near2 (revoming removed removement)))
97	BRS	L97	3	96 and "358"/$.ccls.
98	BRS	L98	43	96 and "250"/$.ccls.
99	BRS	L99	21	96 and "399"/$.ccls.
100	BRS	L100	52	96 and "248"/$.ccls.
101	BRS	L101	18	96 and "359"/$.ccls.
102	BRS	L103	0	102 and scanner
103	BRS	L102	267	96 and "362"/$.ccls.

	Type	L #	Hits	Search Text
104	BRS	L104	4198	(((light adj source) tube bulb lamp) with ((easy easily) near5 (revoming removed removement replaced replacement replacing)))
105	BRS	L105	13	104 and "358"/$.ccls.